

LMK01801BISQX/NOPB

Karolo ea Karolo: **LMK01801BISQX/NOPB**

Moetsi / Mochini: N/A

Tlhaloso ea Sehlahisoa: IC CLK BUF 1:8/1:6 3.1GHZ 48WQFN

Sekepe se Tsoang ho: Hong Kong

Boemo ba RoHS: Tataiso ea mahala / RoHS e lumellanang

Tsela ea Shipment: DHL/Fedex/TNT/UPS/EMS

Datasheets:

 **KENYA TLHATLHOBO** >















Setšoantšo se kanna sa emela.
Sheba lithaloso tsa lintlha tsa sehlahisoa.

Lintlha tsa sehlahisoa

Karolo ea Karolo	LMK01801BISQX/NOPB	Moetsi	N/A
Tlhaloso	IC CLK BUF 1:8/1:6 3.1GHZ 48WQFN	Temo ea mahala ea boemo bo phahameng / boemo ba RoHS	Tataiso ea mahala / RoHS e lumellanang
Leqephe la lintlha			
Tšebeliso ea Voltage	3.15 V ~ 3.45 V	Thapa	Fanout Buffer (Distribution), Divider, Multiplexer
Package ea Lisebelisoa tsa Thepa	48-WQFN (7x7)	Sehlooho	-
Boemo - Boitsebiso: Phatlalato	1:8, 1:6	Packaging	Tape & Reel (TR)
Package / Case	48-WFQFN Exposed Pad	Phatlalato	LVC MOS, LVDS, LVPECL
Mocheso o sebetsang	-40°C ~ 85°C	Palo ea Maeto	2
Mofuta oa ho Thaba	Surface Mount	Mokhoa oa ho Utloisisa Bohloko (MSL)	3 (168 Hours)
Nako ea Moeta-pele e Tloaelehileng	12 Weeks	Temo ea mahala ea boemo bo phahameng / boemo ba RoHS	Lead free / RoHS Compliant
Ho kenya	LVC MOS, LVDS, LVPECL, RF Sinewave	Hangata - Max	3.1GHz
Phapang - Ho kenya: Puo	Yes/Yes	Tlhaloso e qaqileng	Clock Fanout Buffer (Distribution), Divider, Multiplexer IC 1:8, 1:6 3.1GHz 48-WFQFN Exposed Pad
Base Part Number	LMK01801		

Lihlahisoa tse amanang

 <p>LMK01020ISQX/NOPB Bahlahisi: N/A Tlhaloso: IC CLK BUFFER 1:8 1.6GHZ 48WQFN</p> <p>RFQ</p>	 <p>LMK02000EVAL-2 Bahlahisi: N/A Tlhaloso: BOARD EVAL FOR LMK02000-2</p> <p>RFQ</p>
 <p>LMK01801BEVAL/NOPB Bahlahisi: N/A Tlhaloso: BOARD EVAL FOR LMK01801B</p> <p>RFQ</p>	 <p>LMK02000ISQX/NOPB Bahlahisi: N/A Tlhaloso: IC CLOCK CONDITIONER PREC 48WQFN</p> <p>RFQ</p>
 <p>LMK02000EVAL-1 Bahlahisi: N/A Tlhaloso: BOARD EVAL WITH 245.76 VCXO</p> <p>RFQ</p>	 <p>LMK01020ISQ/NOPB Bahlahisi: N/A Tlhaloso: IC CLK BUFFER 1:8 1.6GHZ 48WQFN</p> <p>RFQ</p>
 <p>LMK02002ISQ/NOPB Bahlahisi: N/A Tlhaloso: IC CLOCK CONDITIONER PLL 48WQFN</p> <p>RFQ</p>	 <p>LMK01801BISQ/NOPB Bahlahisi: N/A Tlhaloso: IC CLK BUF 1:8/1:6 3.1GHZ 48WQFN</p> <p>RFQ</p>
 <p>LMK01020ISQE/NOPB Bahlahisi: N/A Tlhaloso: IC CLK BUFFER 1:8 1.6GHZ 48WQFN</p> <p>RFQ</p>	 <p>LMK01801BISQE/NOPB Bahlahisi: N/A Tlhaloso: IC CLK BUF 1:8/1:6 3.1GHZ 48WQFN</p> <p>RFQ</p>
 <p>LMK02000EVAL2 Bahlahisi: N/A Tlhaloso: BOARD EVALUATION FOR LMK02000</p> <p>RFQ</p>	 <p>LMK02000ISQ/NOPB Bahlahisi: N/A Tlhaloso: IC CLOCK CONDITIONER PREC 48WQFN</p> <p>RFQ</p>

Related tags

LMK01801BISQX/NOPB

Theko ea LMK01801BISQX/NOPB

Lethathamo la libuka la LMK01801BISQX/NOPB PDF

Stock ea LMK01801BISQX/NOPB

LMK01801BISQX/NOPB

Mofani oa LMK01801BISQX/NOPB

Litšoantšo tsa LMK01801BISQX/NOPB

Boitsebiso ba LMK01801BISQX/NOPB Download

Reka LMK01801BISQX/NOPB

Mofani oa thepa oa

Mofani oa thepa oa LMK01801BISQX/NOPB

Setšoantšo sa LMK01801BISQX/NOPB

Boitsebiso ba LMK01801BISQX/NOPB

Reka LMK01801BISQX/NOPB

Mofani oa