

### CDC2510PWR

Karolo ea Karolo: **CDC2510PWR**

Tlhaloso ea Sehlahisoa: IC 3.3V PLL CLK-DRVR 24-TSSOP

Boemo ba RoHS: Tataiso ea mahala / RoHS e lumellanang


Datasheets:

Moetsi / Mochini: N/A

Sekepe se Tsoang ho: Hong Kong

Tsela ea Shipment: DHL/Fedex/TNT/UPS/EMS

 **KENYA TLHATLHOBO** >















Setšoantšo se kanna sa emela.  
Sheba lithaloso tsa lintlha tsa sehlahisoa.

#### Lintlha tsa sehlahisoa

<b>Karolo ea Karolo</b>	CDC2510PWR	<b>Moetsi</b>	N/A
<b>Tlhaloso</b>	IC 3.3V PLL CLK-DRVR 24-TSSOP	<b>Temo ea mahala ea boemo bo phahameng / boemo ba RoHS</b>	Tataiso ea mahala / RoHS e lumellanang
<b>Leqephe la lintlha</b>			
<b>Tšebeliso ea Voltage</b>	3 V ~ 3.6 V	<b>Thapa</b>	PLL Clock Driver
<b>Package ea Lisebelisoa tsa Thepa</b>	24-TSSOP	<b>Sehlooho</b>	-
<b>Boemo - Boitsebiso: Phatlalatsa</b>	1:10	<b>Packaging</b>	Cut Tape (CT)
<b>Package / Case</b>	24-TSSOP (0.173", 4.40mm Width)	<b>PLL</b>	Yes with Bypass
<b>Phatlalatsa</b>	Clock	<b>Mabitso a mang</b>	296-13641-1
<b>Mocheso o sebetsang</b>	0°C ~ 70°C	<b>Palo ea Maeto</b>	1
<b>Mofuta oa ho Thaba</b>	Surface Mount	<b>Mokhoa oa ho Utloisisa Bohloko (MSL)</b>	1 (Unlimited)
<b>Temo ea mahala ea boemo bo phahameng / boemo ba RoHS</b>	Lead free / RoHS Compliant	<b>Ho kenya</b>	Clock
<b>Hangata - Max</b>	125MHz	<b>Qala / Iketsetse</b>	No/No
<b>Phapang - Ho kenya: Puo</b>	No/No	<b>Base Part Number</b>	CDC2510

#### Lihlahisoa tse amanang

 <p><b>CDC2516DGGR</b> Bahlahisi: N/A Tlhaloso: IC 3.3V PLL CLK-DRV 3ST 48-TSSOP</p> <p><a href="#">RFQ</a></p>	 <p><b>CDC2516DGGRG4</b> Bahlahisi: N/A Tlhaloso: IC 3.3V PLL CLK-DRVR 48-TSSOP</p> <p><a href="#">RFQ</a></p>
 <p><b>CDC2510CPWRG4</b> Bahlahisi: N/A Tlhaloso: IC 3.3V PLL CLK-DRVR 24-TSSOP</p> <p><a href="#">RFQ</a></p>	 <p><b>CDC2510BPWRG4</b> Bahlahisi: N/A Tlhaloso: IC 3.3V PLL CLK-DRVR 24-TSSOP</p> <p><a href="#">RFQ</a></p>
 <p><b>CDC2510BPWR</b> Bahlahisi: N/A Tlhaloso: IC 3.3V PLL CLK-DRVR 24-TSSOP</p> <p><a href="#">RFQ</a></p>	 <p><b>CDC2536DBG4</b> Bahlahisi: N/A Tlhaloso: IC 3.3V PLL CLK-DRVR 28SSOP</p> <p><a href="#">RFQ</a></p>
 <p><b>CDC2510CPWR</b> Bahlahisi: N/A Tlhaloso: IC 3.3V PLL CLK-DRVR 24-TSSOP</p> <p><a href="#">RFQ</a></p>	 <p><b>CDC2510CPW</b> Bahlahisi: N/A Tlhaloso: IC 3.3V PLL CLK-DRVR 24-TSSOP</p> <p><a href="#">RFQ</a></p>
 <p><b>CDC2536DB</b> Bahlahisi: N/A Tlhaloso: IC 3.3V PLL CLK-DRVR 28-SSOP</p> <p><a href="#">RFQ</a></p>	 <p><b>CDC2510PWRG4</b> Bahlahisi: N/A Tlhaloso: IC 3.3V PLL CLK-DRVR 24-TSSOP</p> <p><a href="#">RFQ</a></p>
 <p><b>CDC2536DBR</b> Bahlahisi: N/A Tlhaloso: IC 3.3V PLL CLK-DRVR 28-SSOP</p> <p><a href="#">RFQ</a></p>	 <p><b>CDC2510CPWG4</b> Bahlahisi: N/A Tlhaloso: IC 3.3V PLL CLK-DRVR 24-TSSOP</p> <p><a href="#">RFQ</a></p>

#### Related tags

CDC2510PWR

Theko ea CDC2510PWR

Lethathamo la libuka la CDC2510PWR PDF

Stock ea CDC2510PWR

CDC2510PWR

Mofani oa CDC2510PWR

Litšoantšo tsa CDC2510PWR

Boitsebiso ba CDC2510PWR Download

Reka CDC2510PWR

Mofani oa thepa oa

Mofani oa thepa oa CDC2510PWR

Setšoantšo sa CDC2510PWR

Boitsebiso ba CDC2510PWR

Reka CDC2510PWR

Mofani oa